

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804
Report August 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180742744	Drinking water Delivery Tap 1	01.08.2018	08:40	21,4	colorless, clear	0,54	7,46	0	0	0	0	0	0
180742745	Drinking water Delivery Tap 2	01.08.2018	07:30	22,0	colorless, clear	0,24	7,30	0	0	0	0	-	0
180742746	Drinking water Delivery Tap 3	01.08.2018	07:40	21,2	colorless, clear	0,58	7,40	0	0	0	0	0	0
180742747	Drinking water Delivery Tap 4	01.08.2018	07:50	20,8	colorless, clear	0,58	7,40	0	0	0	0	22	0
180742748	Tank vehicle KWW 33, clutch pipe delivery	01.08.2018	08:05	26,6	colorless, clear	0,48	8,04	0	0	0	0	0	0
180742749	Tank vehicle KWW 34, clutch pipe delivery	01.08.2018	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
180742750	Tank vehicle KWW 35, clutch pipe delivery	01.08.2018	07:55	25,2	colorless, clear	0,34	7,80	0	1	0	0	0	0
180742751	Tank vehicle KWW 36, clutch pipe delivery	01.08.2018	08:10	23,6	colorless, clear	0,58	7,60	0	0	0	0	0	0
180742752	Tank vehicle KWW 37, clutch pipe delivery	01.08.2018	09:15	24,4	colorless, clear	0,45	7,90	0	0	0	0	0	0
180742753	Tank vehicle KWW 38, clutch pipe delivery	01.08.2018	08:00	24,4	colorless, clear	0,50	7,60	0	0	0	0	0	0
180742754	Tank vehicle KWW 39, clutch pipe delivery	01.08.2018	09:20	25,6	colorless, clear	0,47	7,90	0	0	0	0	0	0
180742018	Tank vehicle KWW 40, clutch pipe delivery	01.08.2018	09:10	24,6	colorless, clear	0,50	7,80	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500592804
Report August 2018**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
180742019	Tank vehicle KWW 41, clutch pipe delivery	01.08.2018	08:25	22,6	colorless, clear	0,52	7,50	0	0	0	0	0	0
180742025	Tank vehicle KWW 42, clutch pipe delivery	01.08.2018	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
180742026	Tank vehicle KWW 43, clutch pipe delivery	01.08.2018	09:30	22,4	colorless, clear	0,80	7,70	0	0	0	0	0	0
180742027	Tank vehicle KWW 44, clutch pipe delivery	01.08.2018	08:40	23,6	colorless, clear	0,38	7,70	0	0	0	0	0	0
180742028	Tank vehicle KWW 45, clutch pipe delivery	01.08.2018	08:20	24,6	colorless, clear	0,40	7,70	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample **180742747** out of limit value: **Pseudomonas aeruginosa**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, August 08, 2018