

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4281360 (April 2019)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
190336665	Drinking water Delivery Tap 1	25.04.2019	08:50	16,1	colorless, clear	0,74	7,62	0	0	0	0	0	0
190336667	Drinking water Delivery Tap 2	25.04.2019	09:15	16,3	colorless, clear	0,78	7,61	0	0	0	0	0	0
190336669	Drinking water Delivery Tap 3	25.04.2019	09:25	16,2	colorless, clear	1,17	7,56	0	0	0	0	0	0
190336670	Drinking water Delivery Tap 4	25.04.2019	09:30	16,4	colorless, clear	0,29	7,62	0	0	0	0	0	0
190336671	Tank vehicle KWW 33, clutch pipe delivery	25.04.2019	08:15	16,1	colorless, clear	0,41	7,84	0	0	0	0	0	0
190336672	Tank vehicle KWW 34, clutch pipe delivery	25.04.2019	08:25	18,0	colorless, clear	0,46	7,84	0	0	0	0	0	0
190336673	Tank vehicle KWW 35, clutch pipe delivery	25.04.2019	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
190336674	Tank vehicle KWW 36, clutch pipe delivery	25.04.2019	08:50	16,3	colorless, clear	0,68	7,87	0	0	0	0	0	0
190336677	Tank vehicle KWW 37, clutch pipe delivery	25.04.2019	08:45	16,9	colorless, clear	0,59	7,72	0	0	0	0	0	0
190336678	Tank vehicle KWW 38, clutch pipe delivery	25.04.2019	08:30	17,5	colorless, clear	0,35	7,73	0	0	0	0	0	0
190336679	Tank vehicle KWW 39, clutch pipe delivery	25.04.2019	08:35	16,1	colorless, clear	0,61	7,85	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4281360 (April 2019)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
190336680	Tank vehicle KWW 40, clutch pipe delivery	25.04.2019	-	-	-	-	-	sampling not possible: tank vehicle in desinfection					
190336681	Tank vehicle KWW 41, clutch pipe delivery	25.04.2019	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
190336682	Tank vehicle KWW 42, clutch pipe delivery	25.04.2019	08:05	17,5	colorless, clear	0,49	7,94	0	0	0	0	0	0
190336683	Tank vehicle KWW 43, clutch pipe delivery	25.04.2019	09:20	16,4	colorless, clear	0,51	7,91	0	0	0	0	0	0
190336684	Tank vehicle KWW 44, clutch pipe delivery	25.04.2019	09:00	17,5	colorless, clear	0,43	7,94	0	0	0	0	0	0
190336685	Tank vehicle KWW 45, clutch pipe delivery	25.04.2019	09:10	16,5	colorless, clear	0,36	8,01	0	0	0	0	1	0
190336687	Tank vehicle KWW 46, clutch pipe delivery	25.04.2019	09:05	17,3	colorless, clear	0,50	7,88	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample 190336685 is out of limit value: **Pseudomonas aeruginosa**

SGS INSTITUT FRESENIUS GmbH

Tausenstein, May 02, 2019

i. A. Andra