

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4456088 (August 2019)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
190938107	Drinking water Delivery Tap 1	29.08.2019	09:55	25.4	colorless, clear	0.86	7.49	0.20	0	0	0	0	0	0
190938137	Drinking water Delivery Tap 2	29.08.2019	10:20	23.6	colorless, clear	0.76	7.53	0.20	0	0	0	0	0	0
190938138	Drinking water Delivery Tap 3	29.08.2019	10:00	24.0	colorless, clear	1.29	7.37	0.20	0	0	0	0	0	0
190938139	Drinking water Delivery Tap 4	29.08.2019	10:30	22.5	colorless, clear	0.64	7.47	0.20	0	0	0	0	0	0
190938140	Tank vehicle KWW 33, clutch pipe delivery	29.08.2019	09:20	25.3	colorless, clear	0.71	7.69	0.20	0	0	0	0	0	0
190938141	Tank vehicle KWW 34, clutch pipe delivery	29.08.2019	09:30	26.3	colorless, clear	0.75	7.77	0.20	0	0	0	0	0	0
190938142	Tank vehicle KWW 35, clutch pipe delivery	29.08.2019	09:10	25.3	colorless, clear	0.93	7.49	0.20	0	0	0	0	0	0
190938143	Tank vehicle KWW 36, clutch pipe delivery	29.08.2019	08:55	24.5	colorless, clear	0.88	7.46	0.20	0	1	0	0	0	0
190938144	Tank vehicle KWW 37, clutch pipe delivery	29.08.2019	09:35	26.3	colorless, clear	0.72	7.63	0.10	0	0	0	0	0	0
190938145	Tank vehicle KWW 38, clutch pipe delivery	29.08.2019	10:10	27.2	colorless, clear	1.03	7.91	0.20	0	0	0	0	0	0
190938146	Tank vehicle KWW 39, clutch pipe delivery	29.08.2019	09:40	26.2	colorless, clear	0.86	7.63	0.20	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4456088 (August 2019)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
190938147	Tank vehicle KWW 40, clutch pipe delivery	29.08.2019	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
190938148	Tank vehicle KWW 41, clutch pipe delivery	29.08.2019	09:05	26,8	colorless, clear	0,70	7,01	0,20	0	0	0	0	0	0
190938149	Tank vehicle KWW 42, clutch pipe delivery	29.08.2019	10:15	25,0	colorless, clear	0,85	7,45	0,10	0	0	0	0	0	0
190938150	Tank vehicle KWW 43, clutch pipe delivery	29.08.2019	08:50	24,5	colorless, clear	0,83	7,69	0,10	0	0	0	0	0	0
190938501	Tank vehicle KWW 44, clutch pipe delivery	29.08.2019	09:40	25,1	colorless, clear	0,83	7,58	0,20	0	0	0	0	0	0
190938502	Tank vehicle KWW 45, clutch pipe delivery	29.08.2019	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
190938503	Tank vehicle KWW 46, clutch pipe delivery	29.08.2019	09:45	25,4	colorless, clear	0,74	7,78	0,20	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, September 06, 2019

i. A. Andra