

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
Report 4946920 (August 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200755280	Drinking water Delivery Tap 1	26.08.2020	09:20	24,3	colorless, clear	0,84	7,66	0,5	0	0	0	0	0	0
200755281	Drinking water Delivery Tap 2	26.08.2020	09:25	25,6	colorless, clear	0,68	7,74	0,5	0	0	0	0	0	0
200755282	Drinking water Delivery Tap 3	26.08.2020	09:30	24,0	colorless, clear	1,00	7,80	0,6	0	0	0	0	0	0
200755283	Drinking water Delivery Tap 4	26.08.2020	09:35	23,5	colorless, clear	0,26	7,80	0,4	0	0	0	0	0	0
200755284	Tank vehicle KWW 36, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200755285	Tank vehicle KWW 38, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200755286	Tank vehicle KWW 39, clutch pipe delivery	26.08.2020	09:00	23,0	colorless, clear	0,58	7,90	0,5	0	0	0	0	0	0
200755287	Tank vehicle KWW 41, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200755288	Tank vehicle KWW 42, clutch pipe delivery	26.08.2020	09:05	23,4	colorless, clear	0,70	8,00	0,5	0	0	0	0	0	0
200755289	Tank vehicle KWW 43, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200755292	Tank vehicle KWW 44, clutch pipe delivery	26.08.2020	08:45	23,0	colorless, clear	0,63	7,56	0,4	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
Report 4946920 (August 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200755293	Tank vehicle KWW 45, clutch pipe delivery	26.08.2020	09:15	22,0	colorless, clear	0,47	7,96	0,4	0	0	0	0	0	0
200755294	Tank vehicle KWW 46, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200755295	Tank vehicle KWW 47, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200755296	Tank vehicle KWW 48, clutch pipe delivery	26.08.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200755297	Tank vehicle KWW 49, clutch pipe delivery	26.08.2020	08:55	23,4	colorless, clear	0,63	7,96	0,7	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, September 08, 2020

*I. A. Andra*