

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Deutsche
 Akkreditierungsstelle
 D-PL-14115-02-00
 D-PL-14115-03-00
 D-PL-14115-06-00
 D-PL-14115-07-00
 D-PL-14115-08-00
 D-PL-14115-09-00
 D-PL-14115-11-00
 D-PL-14115-14-00

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 4977589 (September 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200842161	Drinking water Delivery Tap 1	24.09.2020	09:40	24,2	colorless, clear	0,99	7,56	0,6	0	0	0	0	0	0
200842162	Drinking water Delivery Tap 2	24.09.2020	09:50	23,0	colorless, clear	0,95	7,54	0,5	0	0	0	0	0	0
200842163	Drinking water Delivery Tap 3	24.09.2020	09:55	23,1	colorless, clear	0,61	7,50	0,6	0	1	0	0	0	0
200842164	Drinking water Delivery Tap 4	24.09.2020	10:00	23,3	colorless, clear	0,44	7,53	0,6	0	0	0	0	0	0
200842165	Tank vehicle KWW 36, clutch pipe delivery	24.09.2020	09:55	23,4	colorless, clear	0,84	7,64	1,0	0	0	0	0	0	0
200842166	Tank vehicle KWW 38, clutch pipe delivery	24.09.2020	09:25	23,8	colorless, clear	0,86	7,64	0,7	0	0	0	0	0	0
200842167	Tank vehicle KWW 39, clutch pipe delivery	24.09.2020	09:00	23,4	colorless, clear	0,91	7,70	0,7	0	0	0	0	0	0
200842168	Tank vehicle KWW 41, clutch pipe delivery	24.09.2020	08:40	23,8	colorless, clear	0,59	7,73	0,7	0	0	0	0	0	0
200842169	Tank vehicle KWW 42, clutch pipe delivery	24.09.2020	09:30	24,0	colorless, clear	0,98	7,58	0,6	0	0	0	0	0	0
200842170	Tank vehicle KWW 43, clutch pipe delivery	24.09.2020	08:50	22,8	colorless, clear	0,62	7,97	0,7	0	0	0	0	0	0
200842171	Tank vehicle KWW 44, clutch pipe delivery	24.09.2020	09:15	22,0	colorless, clear	0,71	7,86	0,9	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



DAKKS
 Akkreditierungsstelle
 D-PL-14115-02-00
 D-PL-14115-03-00
 D-PL-14115-06-00
 D-PL-14115-07-00
 D-PL-14115-08-00
 D-PL-14115-10-00
 D-PL-14115-13-00
 D-PL-14115-14-00

Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 4977589 (September 2020)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200842172	Tank vehicle KVVV 45, clutch pipe delivery	24.09.2020	09:40	23,6	colorless, clear	0,91	7,59	0,6	0	0	0	0	0	0
200842173	Tank vehicle KVVV 46, clutch pipe delivery	24.09.2020	08:30	23,1	colorless, clear	0,84	7,73	0,7	0	0	0	0	0	0
200842175	Tank vehicle KVVV 47, clutch pipe delivery	24.09.2020	09:15	22,3	colorless, clear	0,77	7,87	0,5	0	0	0	0	0	0
200842176	Tank vehicle KVVV 48, clutch pipe delivery	24.09.2020	09:10	22,8	colorless, clear	0,45	7,86	0,8	0	0	0	0	0	0
200842177	Tank vehicle KVVV 49, clutch pipe delivery	24.09.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, September 30, 2020

i. A. Audrä