

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Deutsche
 Akkreditierungsstelle
 D-PL-14115-02-00
 D-PL-14115-03-00
 D-PL-14115-06-00
 D-PL-14115-07-00
 D-PL-14115-08-00
 D-PL-14115-10-00
 D-PL-14115-13-00
 D-PL-14115-14-00

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 5026110 (October 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200972953	Drinking water Delivery Tap 1	28.10.2020	09:30	19,1	colorless, clear	0,97	7,64	2,7	0	0	0	0	0	0
200972954	Drinking water Delivery Tap 2	28.10.2020	09:50	18,5	colorless, clear	1,11	7,70	6,1	0	0	0	0	0	0
200972955	Drinking water Delivery Tap 3	28.10.2020	10:00	18,8	colorless, clear	1,50	7,64	8,2	0	1	0	0	0	0
200972956	Drinking water Delivery Tap 4	28.10.2020	10:05	18,3	colorless, clear	0,66	7,70	8,6	0	0	0	0	0	0
200972957	Tank vehicle KWW 36, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is in disinfection					
200972958	Tank vehicle KWW 38, clutch pipe delivery	28.10.2020	08:50	15,4	colorless, clear	0,65	7,82	1,5	0	0	0	0	0	0
200972959	Tank vehicle KWW 39, clutch pipe delivery	28.10.2020	09:00	16,0	colorless, clear	0,88	7,74	1,4	0	0	0	0	0	0
200972960	Tank vehicle KWW 41, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is in disinfection					
200972961	Tank vehicle KWW 42, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200972962	Tank vehicle KWW 43, clutch pipe delivery	28.10.2020	08:35	15,8	colorless, clear	1,07	7,81	2,9	0	0	0	0	0	0
200972963	Tank vehicle KWW 44, clutch pipe delivery	28.10.2020	09:15	13,3	colorless, clear	1,18	7,74	2,9	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 5026110 (October 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200972964	Tank vehicle KWW 45, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200972256	Tank vehicle KWW 46, clutch pipe delivery	28.10.2020	09:40	14.5	colorless, clear	1,06	7,89	5,8	0	0	0	0	0	0
200972257	Tank vehicle KWW 47, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200972258	Tank vehicle KWW 48, clutch pipe delivery	28.10.2020	09:45	17.0	colorless, clear	0,68	7,91	6,5	0	0	0	0	0	0
200972259	Tank vehicle KWW 49, clutch pipe delivery	28.10.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of all testing samples are out of limit value: **turbidity**

The microbiological quality of all other tested parameters are unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, November 04, 2020

I. A. Andrae