

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 5100899 (December 2020)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
201102753	Drinking water Delivery Tap 1	17.12.2020	09:45	13,2	colorless, clear	0,49	7,72	0,5	0	0	0	0	0	0
201102754	Drinking water Delivery Tap 2	17.12.2020	10:15	13,0	colorless, clear	0,36	7,67	0,5	0	0	0	0	0	0
201102755	Drinking water Delivery Tap 3	17.12.2020	10:05	12,0	colorless, clear	0,76	7,73	0,5	0	1	0	0	0	0
201102756	Drinking water Delivery Tap 4	17.12.2020	09:50	13,0	colorless, clear	0,88	7,75	0,6	0	0	0	0	0	0
201102757	Tank vehicle KWW 36, clutch pipe delivery	17.12.2020	09:05	11,4	colorless, clear	0,96	7,63	0,5	0	0	0	0	0	0
201102758	Tank vehicle KWW 38, clutch pipe delivery	17.12.2020	09:10	5,0	colorless, clear	0,75	7,75	0,6	0	0	0	0	0	0
201102759	Tank vehicle KWW 39, clutch pipe delivery	17.12.2020	08:45	13,0	colorless, clear	0,89	7,64	0,5	0	0	0	0	0	0
201102760	Tank vehicle KWW 41, clutch pipe delivery	17.12.2020	09:00	13,1	colorless, clear	0,68	7,67	0,5	0	0	0	0	0	0
201102761	Tank vehicle KWW 42, clutch pipe delivery	17.12.2020	08:35	12,5	colorless, clear	0,95	7,62	0,5	0	1	0	0	0	-
201102762	Tank vehicle KWW 43, clutch pipe delivery	17.12.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
201102763	Tank vehicle KWW 44, clutch pipe delivery	17.12.2020	09:35	12,4	colorless, clear	0,81	7,89	0,5	0	1	0	0	0	-

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 5100899 (December 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
201102764	Tank vehicle KWW 45, clutch pipe delivery	17.12.2020	09:30	12,5	colorless, clear	1,54	7,80	0,6	0	0	0	0	0	0
201102765	Tank vehicle KWW 46, clutch pipe delivery	17.12.2020	09:20	8,0	colorless, clear	0,90	7,84	0,2	0	0	0	0	0	0
201102766	Tank vehicle KWW 47, clutch pipe delivery	17.12.2020	08:55	12,6	colorless, clear	0,66	7,71	0,6	0	0	0	0	0	0
201102767	Tank vehicle KWW 48, clutch pipe delivery	17.12.2020	08:20	12,7	colorless, clear	0,52	7,73	0,6	0	0	0	0	0	0
201102768	Tank vehicle KWW 49, clutch pipe delivery	17.12.2020	08:30	12,6	colorless, clear	0,65	7,71	0,7	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH Taunusstein, December 23, 2020 *i. d. Audia*