

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdiene



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4781056 (April 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200303117	Drinking water Delivery Tap 1	29.04.2020	09:20	18,0	colorless, clear	0,84	7,75	0,2	0	0	0	0	0	0
200303118	Drinking water Delivery Tap 2	29.04.2020	09:30	17,2	colorless, clear	0,60	7,75	<0,1	0	0	0	0	0	0
200303119	Drinking water Delivery Tap 3	29.04.2020	09:35	17,0	colorless, clear	0,60	7,75	<0,1	0	0	0	0	0	0
200303120	Drinking water Delivery Tap 4	29.04.2020	09:45	17,0	colorless, clear	0,68	7,75	0,2	0	0	0	0	0	0
200303121	Tank vehicle KWW 36, clutch pipe delivery	29.04.2020	09:00	18,0	colorless, clear	0,60	7,85	<0,1	0	6	0	0	0	0
200303122	Tank vehicle KWW 37, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200303123	Tank vehicle KWW 38, clutch pipe delivery	29.04.2020	09:15	17,6	colorless, clear	0,38	7,95	<0,1	0	1	0	0	0	0
200303124	Tank vehicle KWW 39, clutch pipe delivery	29.04.2020	08:50	18,4	colorless, clear	0,76	7,88	0,2	0	0	0	0	0	0
200303125	Tank vehicle KWW 40, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200303126	Tank vehicle KWW 41, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					
200303127	Tank vehicle KWW 42, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	sampling not possible: tank vehicle is out of order					

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4781056 (April 2020)**



Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200303128	Tank vehicle KWW 43, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303129	Tank vehicle KWW 44, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303130	Tank vehicle KWW 45, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303131	Tank vehicle KWW 46, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303132	Tank vehicle KWW 47, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303133	Tank vehicle KWW 48, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-
200303134	Tank vehicle KWW 49, clutch pipe delivery	29.04.2020	-	-	-	-	-	-	-	-	-	-	-	-

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, May 06, 2020

J. A. Andra