

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



DAKKS
 Accredited Stelle
 O-PL-14115-02-00
 O-PL-14115-03-00
 O-PL-14115-06-00
 O-PL-14115-08-00
 O-PL-14115-10-00
 O-PL-14115-13-00
 O-PL-14115-14-00

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 4863015 (July 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200614209	Drinking water Delivery Tap 1	02.07.2020	09:05	21,0	colorless, clear	0,90	7,70	0,4	0	0	0	0	0	0
200614210	Drinking water Delivery Tap 2	02.07.2020	09:10	20,6	colorless, clear	1,00	7,70	0,4	0	0	0	0	0	0
200614211	Drinking water Delivery Tap 3	02.07.2020	09:25	22,0	colorless, clear	0,60	7,70	0,4	0	0	0	0	0	0
200614212	Drinking water Delivery Tap 4	02.07.2020	09:30	21,8	colorless, clear	0,46	7,70	0,4	0	0	0	0	0	0
200614217	Tank vehicle KWW 36, clutch pipe delivery	02.07.2020	08:00	21,0	colorless, clear	0,86	7,64	0,3	0	0	0	0	0	0
200614219	Tank vehicle KWW 37, clutch pipe delivery	02.07.2020	-	-	-	-	-	-	sampling not possible: tank vehicle not existent					
200614220	Tank vehicle KWW 38, clutch pipe delivery	02.07.2020	08:40	22,6	colorless, clear	0,82	7,70	0,8	0	10	0	0	0	0
200614221	Tank vehicle KWW 39, clutch pipe delivery	02.07.2020	08:30	24,0	colorless, clear	0,68	7,80	0,3	0	0	0	0	0	0
200614222	Tank vehicle KWW 40, clutch pipe delivery	02.07.2020	-	-	-	-	-	-	sampling not possible: tank vehicle not existent					
200614223	Tank vehicle KWW 41, clutch pipe delivery	02.07.2020	08:55	22,0	colorless, clear	0,82	7,70	0,4	0	0	0	0	0	0
200614224	Tank vehicle KWW 42, clutch pipe delivery	02.07.2020	08:10	22,2	colorless, clear	0,86	7,70	0,5	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Deutsche
 Akkreditierungsstelle
 D-PL-14115-02-00
 D-PL-14115-03-00
 D-PL-14115-06-00
 D-PL-14115-07-00
 D-PL-14115-08-00
 D-PL-14115-10-00
 D-PL-14115-13-00
 D-PL-14115-14-00

**Report on the samples being taken by our field service - Your Order No.: BVD-450006483363
 Report 4863015 (July 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200614225	Tank vehicle KWW 43, clutch pipe delivery	02.07.2020	08:45	22,2	colorless, clear	0,72	7,70	1,30	0	0	0	0	0	0
200614226	Tank vehicle KWW 44, clutch pipe delivery	02.07.2020	08:35	23,2	colorless, clear	0,48	7,86	0,3	0	0	0	0	0	0
200614227	Tank vehicle KWW 45, clutch pipe delivery	02.07.2020	08:20	22,2	colorless, clear	0,80	7,66	0,4	0	0	0	0	0	0
200614228	Tank vehicle KWW 46, clutch pipe delivery	02.07.2020	08:25	22,4	colorless, clear	0,90	7,70	0,4	0	0	0	0	0	0
200614229	Tank vehicle KWW 47, clutch pipe delivery	02.07.2020	08:50	23,6	colorless, clear	0,64	8,00	0,3	0	0	0	0	0	0
200614230	Tank vehicle KWW 48, clutch pipe delivery	02.07.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200614233	Tank vehicle KWW 49, clutch pipe delivery	02.07.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, July 10, 2020

i. A. Andia