

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
Report 4661130 (January 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
191389724	Drinking water Delivery Tap 1	29.01.2020	10:05	12,2	colorless, clear	0,94	7,63	0,3	0	0	0	0	0	0
191389727	Drinking water Delivery Tap 2	29.01.2020	10:15	12,3	colorless, clear	1,23	7,54	0,4	0	0	0	0	0	0
191389728	Drinking water Delivery Tap 3	29.01.2020	10:20	11,5	colorless, clear	0,43	7,57	0,3	0	0	0	0	0	0
191389729	Drinking water Delivery Tap 4	29.01.2020	10:30	12,0	colorless, clear	1,20	7,57	0,3	0	0	0	0	0	0
191389731	Tank vehicle KWW 33, clutch pipe delivery	29.01.2020	-	-	-	-	-	-	sampling not possible: tank vehicle not existent					
191389736	Tank vehicle KWW 34, clutch pipe delivery	29.01.2020	09:50	10,5	colorless, clear	0,96	7,81	0,3	0	0	0	0	0	0
191389737	Tank vehicle KWW 35, clutch pipe delivery	29.01.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
191389738	Tank vehicle KWW 36, clutch pipe delivery	29.01.2020	09:00	12,0	colorless, clear	0,92	7,64	0,3	0	0	0	0	0	0
191389740	Tank vehicle KWW 37, clutch pipe delivery	29.01.2020	09:40	9,0	colorless, clear	0,69	7,86	0,3	0	0	0	0	0	0
191389741	Tank vehicle KWW 38, clutch pipe delivery	29.01.2020	09:45	7,8	colorless, clear	0,76	7,86	0,3	0	0	0	0	0	0
191389742	Tank vehicle KWW 39, clutch pipe delivery	29.01.2020	09:05	10,7	colorless, clear	0,64	7,79	0,3	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
Report 4661130 (January 2020)



Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
191389743	Tank vehicle KWW 40, clutch pipe delivery	29.01.2020	09:25	11,0	colorless, clear	1,19	7,72	0,3	0	0	0	0	0	0
191389747	Tank vehicle KWW 41, clutch pipe delivery	29.01.2020	09:10	11,0	colorless, clear	0,80	7,83	0,3	0	0	0	0	0	0
191389748	Tank vehicle KWW 42, clutch pipe delivery	29.01.2020	08:45	9,4	colorless, clear	0,90	7,74	0,4	0	0	0	0	0	0
191389749	Tank vehicle KWW 43, clutch pipe delivery	29.01.2020	08:30	11,5	colorless, clear	1,05	7,73	0,3	0	0	0	0	0	0
191389750	Tank vehicle KWW 44, clutch pipe delivery	29.01.2020	09:35	8,3	colorless, clear	0,87	7,94	0,4	0	0	0	0	0	0
191389801	Tank vehicle KWW 45, clutch pipe delivery	29.01.2020	09:30	12,1	colorless, clear	0,63	7,71	0,3	0	0	0	0	0	0
191389802	Tank vehicle KWW 46, clutch pipe delivery	29.01.2020	10:00	11,3	colorless, clear	1,11	7,65	0,3	0	0	0	0	0	0
200113135	Tank vehicle KWW 47, clutch pipe delivery	29.01.2020	09:15	11,6	colorless, clear	0,77	7,65	0,4	0	0	0	0	0	0
200113134	Tank vehicle KWW 48, clutch pipe delivery	29.01.2020	08:55	10,7	colorless, clear	0,73	7,65	0,4	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, February 05, 2020

*I. T. Andia*