

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdiene

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4705681 (February 2020)**



Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200076365	Drinking water Delivery Tap 1	19.02.2020	10:05	11,8	colorless, clear	0,82	7,70	0,3	0	0	0	0	0	0
200076366	Drinking water Delivery Tap 2	19.02.2020	10:15	10,8	colorless, clear	0,68	7,62	0,2	0	0	0	0	0	0
200076367	Drinking water Delivery Tap 3	19.02.2020	10:20	12,6	colorless, clear	0,64	7,58	0,2	0	0	0	0	0	0
200076368	Drinking water Delivery Tap 4	19.02.2020	10:25	12,4	colorless, clear	0,68	7,62	0,2	0	0	0	0	0	0
200076372	Tank vehicle KWW 36, clutch pipe delivery	19.02.2020	09:25	9,8	colorless, clear	0,51	7,88	0,3	0	0	0	0	0	0
200076374	Tank vehicle KWW 37, clutch pipe delivery	19.02.2020	09:20	10,4	colorless, clear	0,50	7,89	0,2	0	0	0	0	0	0
200076376	Tank vehicle KWW 38, clutch pipe delivery	19.02.2020	09:50	10,0	colorless, clear	0,48	7,90	0,3	0	0	0	0	0	0
200076377	Tank vehicle KWW 39, clutch pipe delivery	19.02.2020	09:05	10,4	colorless, clear	0,48	7,80	0,4	0	0	0	0	0	0
200076378	Tank vehicle KWW 40, clutch pipe delivery	19.02.2020	09:45	10,6	colorless, clear	0,48	7,86	0,3	0	0	0	0	0	0
200076379	Tank vehicle KWW 41, clutch pipe delivery	19.02.2020	09:00	10,6	colorless, clear	0,60	7,60	0,5	0	0	0	0	0	0
200076380	Tank vehicle KWW 42, clutch pipe delivery	19.02.2020	09:10	10,4	colorless, clear	0,48	7,66	0,8	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4705681 (February 2020)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200076381	Tank vehicle KWW 43, clutch pipe delivery	19.02.2020	09:40	12,0	colorless, clear	0,65	7,60	0,2	0	0	0	0	0	0
200076382	Tank vehicle KWW 44, clutch pipe delivery	19.02.2020	10:00	11,0	colorless, clear	0,38	7,82	<0,1	0	0	0	0	0	0
200076383	Tank vehicle KWW 45, clutch pipe delivery	19.02.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200076384	Tank vehicle KWW 46, clutch pipe delivery	19.02.2020	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
200126502	Tank vehicle KWW 47, clutch pipe delivery	19.02.2020	09:30	11,0	colorless, clear	0,78	7,60	0,6	0	0	0	0	0	0
200126503	Tank vehicle KWW 48, clutch pipe delivery	19.02.2020	09:15	11,0	colorless, clear	0,56	7,80	0,7	0	0	0	0	0	0
200076370	Tank vehicle KWW 49, clutch pipe delivery	19.02.2020	08:45	13,0	colorless, clear	0,58	7,62	<0,1	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, March 05, 2020

I. J. Andra