

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



DAKKS
 Accredited
 D-PL-14115-02-00
 D-PL-14115-03-00
 D-PL-14115-04-00
 D-PL-14115-05-00
 D-PL-14115-06-00
 D-PL-14115-07-00
 D-PL-14115-08-00
 D-PL-14115-09-00
 D-PL-14115-10-00
 D-PL-14115-11-00
 D-PL-14115-12-00
 D-PL-14115-13-00
 D-PL-14115-14-00
 D-PL-14115-15-00

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
 Report 4751516 (March 2020)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200266223	Drinking water Delivery Tap 1	31.03.2020	10:20	13,5	colorless, clear	0,71	7,69	0,2	0	0	0	0	0	0
200266264	Drinking water Delivery Tap 2	31.03.2020	10:15	13,8	colorless, clear	0,97	7,66	0,1	0	0	0	0	0	0
200266265	Drinking water Delivery Tap 3	31.03.2020	10:05	14,0	colorless, clear	1,20	7,67	0,2	0	0	0	0	0	0
200266266	Drinking water Delivery Tap 4	31.03.2020	10:00	13,7	colorless, clear	1,29	7,68	0,5	0	0	0	0	0	0
200266267	Tank vehicle KWW 36, clutch pipe delivery	31.03.2020	09:40	12,5	colorless, clear	0,75	7,76	0,2	0	0	0	0	0	0
200266268	Tank vehicle KWW 37, clutch pipe delivery	31.03.2020	09:00	13,3	colorless, clear	0,83	7,74	0,2	0	0	0	0	0	0
200266270	Tank vehicle KWW 38, clutch pipe delivery	31.03.2020	08:55	13,0	colorless, clear	0,72	7,72	<0,1	0	0	0	0	0	0
200266271	Tank vehicle KWW 39, clutch pipe delivery	31.03.2020	08:45	11,1	colorless, clear	0,45	7,83	<0,1	0	0	0	0	0	0
200266272	Tank vehicle KWW 40, clutch pipe delivery	31.03.2020	09:25	11,9	colorless, clear	0,69	7,74	0,1	0	0	0	0	0	0
200266273	Tank vehicle KWW 41, clutch pipe delivery	31.03.2020	08:50	10,5	colorless, clear	0,44	7,79	0,1	0	0	0	0	0	0
200266274	Tank vehicle KWW 42, clutch pipe delivery	31.03.2020	09:20	12,0	colorless, clear	1,14	7,75	0,2	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500648363
Report 4751516 (March 2020)



DAKKS
Akreditierungsstelle
D-PL-14115-02-00
D-PL-14115-03-00
D-PL-14115-04-00
D-PL-14115-05-00
D-PL-14115-06-00
D-PL-14115-07-00
D-PL-14115-08-00
D-PL-14115-09-00
D-PL-14115-10-00
D-PL-14115-11-00
D-PL-14115-12-00
D-PL-14115-13-00
D-PL-14115-14-00
D-PL-14115-15-00

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
200266275	Tank vehicle KWW 43, clutch pipe delivery	31.03.2020	-	-	-	-	-	-	-	-	-	-	-	-
200266276	Tank vehicle KWW 44, clutch pipe delivery	31.03.2020	09:50	12,0	colorless, clear	0,97	7,73	0,2	0	0	0	0	0	0
200266278	Tank vehicle KWW 45, clutch pipe delivery	31.03.2020	09:15	11,5	colorless, clear	0,54	7,82	0,1	0	0	0	0	0	0
200266279	Tank vehicle KWW 46, clutch pipe delivery	31.03.2020	09:35	9,0	colorless, clear	0,33	7,80	0,2	0	0	0	0	0	0
200266285	Tank vehicle KWW 47, clutch pipe delivery	31.03.2020	09:45	12,5	colorless, clear	0,85	7,75	0,1	0	0	0	0	0	0
200266221	Tank vehicle KWW 48, clutch pipe delivery	31.03.2020	08:35	10,3	colorless, clear	0,55	7,71	0,1	0	0	0	0	0	0
200266222	Tank vehicle KWW 49, clutch pipe delivery	31.03.2020	08:30	11,4	colorless, clear	0,56	7,73	0,2	0	0	0	0	0	0

sampling not possible: tank vehicle in repair shop

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, April 07, 2020

i. d. A. Andriä