

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
Report 5401241 (July 2021)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210772148	Drinking water Delivery Tap 1	28.07.2021	10:15	21,2	colorless, clear	1,30	7,68	0,4	0	0	0	0	0	0
210772149	Drinking water Delivery Tap 2	28.07.2021	10:20	21,0	colorless, clear	1,30	7,66	0,3	0	0	0	0	0	0
210772301	Drinking water Delivery Tap 3	28.07.2021	10:30	20,8	colorless, clear	0,96	7,66	0,4	0	0	0	0	0	0
210772302	Drinking water Delivery Tap 4	28.07.2021	10:35	20,8	colorless, clear	1,16	7,68	0,4	0	0	0	0	0	0
210772303	Tank vehicle KWW 36, clutch pipe delivery	28.07.2021	09:15	21,2	colorless, clear	0,90	7,68	0,3	0	0	0	0	0	0
210772304	Tank vehicle KWW 38, clutch pipe delivery	28.07.2021	09:20	21,6	colorless, clear	0,74	7,90	0,4	0	0	0	0	0	0
210772305	Tank vehicle KWW 39, clutch pipe delivery	28.07.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210772306	Tank vehicle KWW 41, clutch pipe delivery	28.07.2021	09:45	20,8	colorless, clear	0,70	7,72	0,4						
210772307	Tank vehicle KWW 42, clutch pipe delivery	28.07.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210772308	Tank vehicle KWW 43, clutch pipe delivery	28.07.2021	09:05	21,6	colorless, clear	0,76	7,84	0,3	0	0	0	0	0	0
210772309	Tank vehicle KWW 44, clutch pipe delivery	28.07.2021	09:00	21,6	colorless, clear	0,78	7,70	0,3	0	0	0	0	0	0

Freigegeben: 09.08.2021 i. A. Fabrice / i. A. Schatzel / Bodenberatung

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
Report 5401241 (July 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210772310	Tank vehicle KWW 45, clutch pipe delivery	28.07.2021	09:30	21,2	colorless, clear	0,76	7,80	0,3	0	0	0	0	0	0
210772311	Tank vehicle KWW 46, clutch pipe delivery	28.07.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210772312	Tank vehicle KWW 47, clutch pipe delivery	28.07.2021	10:00	22,0	colorless, clear	0,70	8,08	0,4	0	0	0	0	0	0
210772313	Tank vehicle KWW 48, clutch pipe delivery	28.07.2021	09:45	22,2	colorless, clear	0,80	7,60	0,4	0	0	0	0	0	0
210772314	Tank vehicle KWW 49, clutch pipe delivery	28.07.2021	08:40	20,6	colorless, clear	0,70	7,80	0,3	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, August 09, 2021

i. A. J. H. G. T. M.

Freigegeben: 09.08.2021 i. A. Gabriele Schätzel Kundenbetreuung.