

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
 Report 5167572 (February 2021)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210132563	Drinking water Delivery Tap 1	11.02.2021	10:00	8,7	colorless, clear	1,22	7,72	<0,1	0	0	0	0	0	0
210132564	Drinking water Delivery Tap 2	11.02.2021	10:10	9,1	colorless, clear	1,20	7,64	<0,1	0	0	0	0	0	0
210132565	Drinking water Delivery Tap 3	11.02.2021	10:15	8,8	colorless, clear	1,19	7,60	<0,1	0	0	0	0	0	0
210132566	Drinking water Delivery Tap 4	11.02.2021	10:20	8,7	colorless, clear	1,18	7,56	<0,1	0	0	0	0	0	0
210132567	Tank vehicle KWW 36, clutch pipe delivery	11.02.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210132568	Tank vehicle KWW 38, clutch pipe delivery	11.02.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210132569	Tank vehicle KWW 39, clutch pipe delivery	11.02.2021	08:45	8,0	colorless, clear	1,17	7,60	0,9	0	0	0	0	0	0
210132570	Tank vehicle KWW 41, clutch pipe delivery	11.02.2021	09:00	9,0	colorless, clear	1,27	7,64	0,1	0	0	0	0	0	0
210132571	Tank vehicle KWW 42, clutch pipe delivery	11.02.2021	08:55	7,5	colorless, clear	1,20	7,68	0,2	0	0	0	0	0	0
210132572	Tank vehicle KWW 43, clutch pipe delivery	11.02.2021	09:20	7,0	colorless, clear	1,03	7,79	0,4	0	0	0	0	0	0
210132573	Tank vehicle KWW 44, clutch pipe delivery	11.02.2021	09:40	6,9	colorless, clear	0,98	7,77	0,1	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
 Report 5167572 (February 2021)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210132574	Tank vehicle KWW 45, clutch pipe delivery	11.02.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210132575	Tank vehicle KWW 46, clutch pipe delivery	11.02.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210132576	Tank vehicle KWW 47, clutch pipe delivery	11.02.2021	09:05	7,5	colorless, clear	1,12	7,74	0,1	0	0	0	0	0	0
210132577	Tank vehicle KWW 48, clutch pipe delivery	11.02.2021	09:15	9,4	colorless, clear	1,29	7,69	0,2	0	0	0	0	0	0
210132578	Tank vehicle KWW 49, clutch pipe delivery	11.02.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, February 19, 2021

I. A. Andra