

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
Report 5230729 (March 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210166634	Drinking water Delivery Tap 1	30.03.2021	10:20	10,8	colorless, clear	0,76	7,65	1,3	0	0	0	0	0	0
210166635	Drinking water Delivery Tap 2	30.03.2021	10:15	10,7	colorless, clear	0,87	7,66	0,3	0	0	0	0	0	0
210166614	Drinking water Delivery Tap 3	30.03.2021	10:05	10,7	colorless, clear	0,50	7,69	0,3	0	0	0	0	0	0
210166615	Drinking water Delivery Tap 4	30.03.2021	09:55	10,7	colorless, clear	0,71	7,73	0,3	0	0	0	0	0	0
210166616	Tank vehicle KWW 36, clutch pipe delivery	30.03.2021	09:15	10,6	colorless, clear	0,64	7,74	0,3	0	0	0	0	0	0
210166617	Tank vehicle KWW 38, clutch pipe delivery	30.03.2021	08:25	13,5	colorless, clear	0,48	7,87	0,3	0	0	0	0	0	0
210166618	Tank vehicle KWW 39, clutch pipe delivery	30.03.2021	08:40	11,0	colorless, clear	0,67	7,71	0,4	0	0	0	0	0	0
210166622	Tank vehicle KWW 41, clutch pipe delivery	30.03.2021	09:40	10,7	colorless, clear	0,65	7,72	0,4	0	0	0	0	0	0
210166623	Tank vehicle KWW 42, clutch pipe delivery	30.03.2021	08:50	14,5	colorless, clear	0,52	7,65	0,3	0	0	0	0	0	0
210166624	Tank vehicle KWW 43, clutch pipe delivery	30.03.2021	09:10	12,5	colorless, clear	0,51	7,73	0,3	0	0	0	0	0	0
210166625	Tank vehicle KWW 44, clutch pipe delivery	30.03.2021	08:30	12,8	colorless, clear	0,68	7,83	0,3	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



DAKKS  
Deutscher  
Akkreditierungsdienst  
D-PL-14115-02-00  
D-PL-14115-03-00  
D-PL-14115-06-00  
D-PL-14115-07-00  
D-PL-14115-08-00  
D-PL-14115-10-00  
D-PL-14115-13-00  
D-PL-14115-14-00

**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
Report 5230729 (March 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210166627	Tank vehicle KWW 45, clutch pipe delivery	30.03.2021	-	-	-	-	-	-	-	-	-	-	-	-
210166628	Tank vehicle KWW 46, clutch pipe delivery	30.03.2021	08:45	10,9	colorless, clear	0,68	7,66	0,3	0	0	0	0	0	0
210166629	Tank vehicle KWW 47, clutch pipe delivery	30.03.2021	09:20	16,0	colorless, clear	0,41	7,74	0,3	0	0	0	0	0	0
210166630	Tank vehicle KWW 48, clutch pipe delivery	30.03.2021	09:25	13,9	colorless, clear	0,57	7,77	0,3	0	0	0	0	0	0
210166634	Tank vehicle KWW 49, clutch pipe delivery	30.03.2021	09:00	10,9	colorless, clear	0,52	7,71	0,3	0	0	0	0	0	0

sampling not possible: tank vehicle in repair shop

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, April 07, 2021

*I. A. Andia*