

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
Report 5273489 (April 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210323089	Drinking water Delivery Tap 1	29.04.2021	09:25	13,7	colorless, clear	-	7,75	0,2	0	0	0	0	0	0
210323090	Drinking water Delivery Tap 2	29.04.2021	09:50	14,2	colorless, clear	1,00	7,76	0,2	0	0	0	0	0	0
210323091	Drinking water Delivery Tap 3	29.04.2021	10:00	13,7	colorless, clear	0,70	7,71	0,3	0	0	0	0	0	0
210323092	Drinking water Delivery Tap 4	29.04.2021	10:05	14,0	colorless, clear	0,70	7,73	0,3	0	0	0	0	0	0
210323093	Tank vehicle KWW 36, clutch pipe delivery	29.04.2021	08:50	15,0	colorless, clear	0,62	7,82	0,2	0	3	0	0	0	0
210323094	Tank vehicle KWW 38, clutch pipe delivery	29.04.2021	09:05	14,6	colorless, clear	0,67	7,82	0,2	0	0	0	0	0	0
210323095	Tank vehicle KWW 39, clutch pipe delivery	29.04.2021	08:55	14,0	colorless, clear	0,12	8,25	1,2	330	110	0	0	201	0
210323096	Tank vehicle KWW 41, clutch pipe delivery	29.04.2021	09:10	13,9	colorless, clear	0,95	7,70	0,2	0	0	0	0	0	0
210323097	Tank vehicle KWW 42, clutch pipe delivery	29.04.2021	08:15	17,2	colorless, clear	0,03	7,96	0,1	0	330	0	0	5	0
210323098	Tank vehicle KWW 43, clutch pipe delivery	29.04.2021	08:45	13,4	colorless, clear	1,11	7,72	0,2	0	0	0	0	0	0
210323099	Tank vehicle KWW 44, clutch pipe delivery	29.04.2021	09:15	14,3	colorless, clear	0,68	7,75	0,2	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378
Report 5273489 (April 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210323100	Tank vehicle KWW 45, clutch pipe delivery	29.04.2021	09:00	13,5	colorless, clear	1,10	7,65	0,2	0	0	0	0	0	0
210323201	Tank vehicle KWW 46, clutch pipe delivery	29.04.2021	08:35	13,5	colorless, clear	0,83	7,74	0,2	0	0	0	0	0	0
210323202	Tank vehicle KWW 47, clutch pipe delivery	29.04.2021	09:35	14,0	colorless, clear	0,69	7,84	0,2	0	0	0	0	0	0
210323203	Tank vehicle KWW 48, clutch pipe delivery	29.04.2021	09:30	14,5	colorless, clear	0,74	7,94	0,2	0	0	0	0	0	0
210323204	Tank vehicle KWW 49, clutch pipe delivery	29.04.2021	08:40	13,5	colorless, clear	0,80	7,67	0,2	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample **210323095** is out of limit value: **turbidity, KBE 20 °C, KBE 36 °C, Pseudomonas aeruginosa**
 According to the investigations of the German Drinking Water Regulation the following parameter of the testing sample **210323097** is out of limit value: **KBE 36 °C, Pseudomonas aeruginosa**
 The microbiological quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taunusstein, May 07, 2021

I. A. Andig