

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
Report 5442296 (August 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210881995	Drinking water Delivery Tap 1	26.08.2021	09:50	20,4	colorless, clear	0,20	7,62	0,3	0	0	0	0	0	0
210881996	Drinking water Delivery Tap 2	26.08.2021	09:50	20,0	colorless, clear	0,28	7,60	0,3	0	0	0	0	0	0
210882027	Drinking water Delivery Tap 3	26.08.2021	10:00	20,2	colorless, clear	0,44	7,60	0,3	0	0	0	0	0	0
210882028	Drinking water Delivery Tap 4	26.08.2021	10:15	19,8	colorless, clear	0,30	7,60	0,3	0	0	0	0	0	0
210882029	Tank vehicle KWW 36, clutch pipe delivery	26.08.2021	09:10	19,0	colorless, clear	0,26	7,80	0,3	0	0	0	0	0	0
210882030	Tank vehicle KWW 38, clutch pipe delivery	26.08.2021	-	-	-	-	-	-	<b>sampling not possible: tank vehicle is out of order</b>					
210882031	Tank vehicle KWW 39, clutch pipe delivery	26.08.2021	09:45	20,40	colorless, clear	0,28	7,92	0,3	0	0	0	0	0	0
210882032	Tank vehicle KWW 41, clutch pipe delivery	26.08.2021	08:30	21,3	colorless, clear	0,44	7,70	0,3	0	0	0	0	0	0
210882033	Tank vehicle KWW 42, clutch pipe delivery	26.08.2021	08:35	21,00	colorless, clear	0,48	7,60	0,3	0	0	0	0	0	0
210882034	Tank vehicle KWW 43, clutch pipe delivery	26.08.2021	09:35	19,6	colorless, clear	0,56	7,84	0,3	0	0	0	0	0	0
210882035	Tank vehicle KWW 44, clutch pipe delivery	26.08.2021	-	-	-	-	-	-	<b>sampling not possible: tank vehicle in repair shop</b>					

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
Report 5442296 (August 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
210882036	Tank vehicle KWW 45, clutch pipe delivery	26.08.2021	08:50	20,0	colorless, clear	0,55	7,76	0,3	0	0	0	0	0	0
210882037	Tank vehicle KWW 46, clutch pipe delivery	26.08.2021	10:25	20,00	colorless, clear	0,60	8,00	0,3	0	0	0	0	0	0
210882038	Tank vehicle KWW 47, clutch pipe delivery	26.08.2021	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
210882039	Tank vehicle KWW 48, clutch pipe delivery	26.08.2021	09:20	20,0	colorless, clear	0,50	7,80	0,3	0	0	0	0	0	0
210882040	Tank vehicle KWW 49, clutch pipe delivery	26.08.2021	09:35	21,4	colorless, clear	0,48	7,92	0,3	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, September 08, 2021

*I. A. Andra*