

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
 Report 5484198 (September 2021)

| Sample ID | Sample designation                        | Sampling day | Sampling time | Water temperature °C | Description      | Free chlorine mg/l | pH-value | turbidity | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|----------|-----------|--|--|---|------------------------------------|---|--------------------------------------|
| 210985853 | Drinking water Delivery Tap 1             | 29.09.2021   | 09:05         | 19,0                 | colorless, clear | 0,70               | 7,50     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985854 | Drinking water Delivery Tap 2             | 29.09.2021   | 09:10         | 19,2                 | colorless, clear | 0,74               | 7,52     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985855 | Drinking water Delivery Tap 3             | 29.09.2021   | 09:15         | 19,6                 | colorless, clear | 0,80               | 7,52     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985856 | Drinking water Delivery Tap 4             | 29.09.2021   | 09:20         | 19,2                 | colorless, clear | 0,50               | 7,60     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985857 | Tank vehicle KWW 36, clutch pipe delivery | 29.09.2021   | -             | -                    | -                | -                  | -        | -         | sampling not possible: tank vehicle in repair shop         |  |   |                                    |   |                                      |
| 210985858 | Tank vehicle KWW 38, clutch pipe delivery | 29.09.2021   | 08:55         | 16,0                 | colorless, clear | 0,60               | 7,90     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985859 | Tank vehicle KWW 39, clutch pipe delivery | 29.09.2021   | 08:50         | 18,80                | colorless, clear | 0,68               | 7,60     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985860 | Tank vehicle KWW 41, clutch pipe delivery | 29.09.2021   | 08:25         | 18,0                 | colorless, clear | 0,63               | 7,70     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985861 | Tank vehicle KWW 42, clutch pipe delivery | 29.09.2021   | 08:35         | 13,40                | colorless, clear | 0,64               | 7,70     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985862 | Tank vehicle KWW 43, clutch pipe delivery | 29.09.2021   | 08:30         | 17,8                 | colorless, clear | 0,56               | 7,80     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985863 | Tank vehicle KWW 44, clutch pipe delivery | 29.09.2021   | -             | -                    | -                | -                  | -        | -         | sampling not possible: tank vehicle in repair shop         |  |   |                                    |   |                                      |

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500731378  
Report 5484198 (September 2021)**

| Sample ID | Sample designation                        | Sampling day | Sampling time | Water temperature °C | Description      | Free chlorine mg/l | pH-value | turbidity | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|----------|-----------|--|--|---|------------------------------------|---|--------------------------------------|
| 210985864 | Tank vehicle KWW 45, clutch pipe delivery | 29.09.2021   | 08:40         | 18,0                 | colorless, clear | 0,65               | 7,70     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985865 | Tank vehicle KWW 46, clutch pipe delivery | 29.09.2021   | 09:25         | 18,00                | colorless, clear | 0,54               | 8,00     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985866 | Tank vehicle KWW 47, clutch pipe delivery | 29.09.2021   | 08:25         | 17,0                 | colorless, clear | 0,68               | 7,80     | 0,3       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |
| 210985867 | Tank vehicle KWW 48, clutch pipe delivery | 29.09.2021   | 08:30         | 18,6                 | colorless, clear | 0,60               | 7,70     | 0,2       | 1  | 3  | 0   | 0                                  | 0   | 0                                    |
| 210985868 | Tank vehicle KWW 49, clutch pipe delivery | 29.09.2021   | 08:15         | 19,0                 | colorless, clear | 0,78               | 7,50     | 0,2       | 0  | 0  | 0   | 0                                  | 0   | 0                                    |

**Assessment:**

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, October 06, 2021

*i. X. Andra*