

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
report 5541989 (Oktober 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
211107561	Drinking water Delivery Tap 1	27.10.2021	10:20	14,8	colorless, clear	0,82	7,50	0,20	0	0	0	0	0	0
211107562	Drinking water Delivery Tap 2	27.10.2021	10:30	14,8	colorless, clear	0,90	7,62	0,20	0	0	0	0	0	0
211107563	Drinking water Delivery Tap 3	27.10.2021	11:00	15,0	colorless, clear	0,92	7,68	0,20	0	0	0	0	0	0
211107564	Drinking water Delivery Tap 4	27.10.2021	11:10	15,2	colorless, clear	1,00	7,60	0,20	0	0	0	0	0	0
211107566	Tank vehicle KWW 36, clutch pipe delivery	27.10.2021	-	-	-	-	-	-	<b>sampling not possible: tank vehicle in repair shop</b>					
211107567	Tank vehicle KWW 38, clutch pipe delivery	27.10.2021	10:50	15,4	colorless, clear	0,86	7,60	0,20	0	0	0	0	0	0
211107568	Tank vehicle KWW 39, clutch pipe delivery	27.10.2021	10:00	13,8	colorless, clear	0,56	7,80	0,20	0	0	0	0	0	0
211107569	Tank vehicle KWW 41, clutch pipe delivery	27.10.2021	09:55	15,2	colorless, clear	0,72	7,56	0,30	0	0	0	0	0	0
211107570	Tank vehicle KWW 42, clutch pipe delivery	27.10.2021	-	-	-	-	-	-	<b>sampling not possible: tank vehicle in repair shop</b>					
211107571	Tank vehicle KWW 43, clutch pipe delivery	27.10.2021	08:40	14,8	colorless, clear	0,52	7,38	0,20	0	0	0	0	0	0
211107572	Tank vehicle KWW 44, clutch pipe delivery	27.10.2021	09:35	14,6	colorless, clear	0,16	7,50	0,20	0	0	0	0	0	0



To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste



**Report on the samples being taken by our field service - Your Order No.: BVD-4500648363  
report 5541989 (October 2021)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	turbidity	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 2°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
211107573	Tank vehicle KWW 45, clutch pipe delivery	27.10.2021	-	-	-	-	-	-	<b>sampling not possible: tank vehicle in repair shop</b>					
211107574	Tank vehicle KWW 46, clutch pipe delivery	27.10.2021	10:05	15,0	colorless, clear	0,80	7,70	0,30	0	0	0	0	0	0
211107575	Tank vehicle KWW 47, clutch pipe delivery	27.10.2021	09:25	15,0	colorless, clear	0,56	7,70	0,20	0	0	0	0	0	0
211107576	Tank vehicle KWW 48, clutch pipe delivery	27.10.2021	09:40	15,2	colorless, clear	0,82	7,50	0,20	0	0	0	0	0	0
211107577	Tank vehicle KWW 49, clutch pipe delivery	27.10.2021	09:15	14,6	colorless, clear	0,60	7,80	0,30	0	0	0	0	0	0

**Assessment:**

The microbiological quality of all other tested parameters are unobjectionable according to German drinking water regulations as far as examined.

**SGS INSTITUT FRESENIUS GmbH**

Tausenstein, November, 15, 2021

*i.A. f. Schätzel*