



To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500790807
report 6566176 (September 2023)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	Turbidity NTU	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
method					DIN EN ISO 7887 2012-04	DIN EN ISO 7393-2 2004-04	DIN EN ISO 10523 2012-04	DIN EN ISO 7027 2016-11	TrinkwV § 43 Absatz (3.2) 2023-06	TrinkwV § 43 Absatz (3.2) 2023-06	DIN EN ISO 9308-2 2014-6	DIN EN ISO 9308-2 2014-6	ISO 16266-2 2018-07	DIN EN ISO 7899-2 2000-11
230844937	Drinking water Delivery Tap 1	28.09.2023	10:30	18,5	colorless, clear	0,78	7,65	0,3	0	0	0	0	0	0
230844938	Drinking water Delivery Tap 2	28.09.2023	10:40	18,5	colorless, clear	0,69	7,63	0,3	0	0	0	0	0	0
230844971	Drinking water Delivery Tap 3	28.09.2023	10:50	18,5	colorless, clear	0,75	7,63	0,3	0	0	0	0	0	0
230844973	Drinking water Delivery Tap 4	28.09.2023	11:00	18,4	-	0,71	7,63	0,2	0	0	0	0	0	0
230844974	Tank vehicle KWW 36, clutch pipe delivery	28.09.2023	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
230844975	Tank vehicle KWW 38, clutch pipe delivery	28.09.2023	10:15	18,9	colorless, clear	0,60	7,74	0,6	0	0	0	0	0	0
230844976	Tank vehicle KWW 39, clutch pipe delivery	28.09.2023	09:00	18,5	colorless, clear	0,50	7,66	0,3	0	0	0	0	0	0
230844977	Tank vehicle KWW 41, clutch pipe delivery	28.09.2023	08:50	17,7	colorless, clear	0,61	7,79	0,8	0	0	0	0	0	0
230844978	Tank vehicle KWW 42, clutch pipe delivery	28.09.2023	09:15	18,8	colorless, clear	0,52	7,77	0,5	0	0	0	0	0	0
230844979	Tank vehicle KWW 43, clutch pipe delivery	28.09.2023	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
230844980	Tank vehicle KWW 44, clutch pipe delivery	28.09.2023	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
230844981	Tank vehicle KWW 45, clutch pipe delivery	28.09.2023	09:30	19,4	colorless, clear	0,55	7,74	1,3	0	0	0	0	0	0
230844982	Tank vehicle KWW 46, clutch pipe delivery	28.09.2023	09:20	18,8	colorless, clear	0,68	7,61	0,6	0	0	0	0	0	0

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500790807
report 6566176 (September 2023)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	Turbidity NTU	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
230844983	Tank vehicle KWW 47, clutch pipe delivery	28.09.2023	09:40	19,8	colorless, clear	0,55	7,66	0,9	0	0	0	0	0	0
230844984	Tank vehicle KWW 48, clutch pipe delivery	28.09.2023	10:00	19,5	colorless, clear	0,53	7,82	1,4	0	0	0	0	0	0
230844985	Tank vehicle KWW 49, clutch pipe delivery	28.09.2023	09:10	20,3	colorless, clear	0,64	7,73	0,5	0	0	0	0	0	0
230845007	Tank vehicle KWW 50, clutch pipe delivery	28.09.2023	08:45	19,5	colorless, clear	0,51	8,04	0,6	0	0	0	0	0	0

Assessment:

According to the investigations of the German Drinking Water Regulation the following parameter of the testing samples **230844981** and **230844984** are out of limit value: **Turbidity**

The quality of all other tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, October 13th, 2023



I.A. B. Schmidt

The laboratory sites of the SGS group Germany according to the abbreviations mentioned above including the corresponding accreditation process numbers are listed at <http://www.institut-fresenius.de/filestore/69/labstandortkuerzelsgs.pdf>.

*** End of test report ***

This document is issued by the Company subject to its General Conditions of Service (www.sgs.com). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein. This document is an original. If the document is submitted digitally, it is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its client and this document does not exonerate parties to a transaction from exercising all their rights and under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.