



To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500790807
report 6782611 (February 2024)**

| Sample ID | Sample designation | Sampling day | Sampling time | Water temperature °C | Description | Free chlorine mg/l | pH-value | Turbidity NTU | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|-------------------------|---------------------------|--------------------------|-------------------------|--|--|---|------------------------------------|---|--------------------------------------|
| method | | | | DIN 38404-4 1976-12 | DIN EN ISO 7887 2012-04 | DIN EN ISO 7393-2 2004-04 | DIN EN ISO 10523 2012-04 | DIN EN ISO 7027 2016-11 | TrinkwV § 43 Absatz (3.2) 2023-06 | TrinkwV § 43 Absatz (3.2) 2023-06 | DIN EN ISO 9308-2 2014-6 | DIN EN ISO 9308 2 2014-6 | ISO 16286-2 2018-07 | DIN EN ISO 7899-2 2000-11 |
| 240088123 | Drinking water Delivery Tap 1 | 28.02.2024 | 10:40 | 11,3 | colorless, clear | 1,12 | 7,65 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088126 | Drinking water Delivery Tap 2 | 28.02.2024 | 10:25 | 10,9 | colorless, clear | 1,02 | 7,82 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088130 | Drinking water Delivery Tap 3 | 28.02.2024 | 10:35 | 11,0 | colorless, clear | 1,01 | 7,65 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088132 | Drinking water Delivery Tap 4 | 28.02.2024 | 10:50 | 11,2 | colorless, clear | 0,99 | 7,55 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088135 | Tank vehicle KWW 36, clutch pipe delivery | 28.02.2024 | 08:40 | 9,9 | colorless, clear | 0,63 | 7,91 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088139 | Tank vehicle KWW 38, clutch pipe delivery | 28.02.2024 | 08:55 | 9,9 | colorless, clear | 0,74 | 7,93 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088141 | Tank vehicle KWW 39, clutch pipe delivery | 28.02.2024 | 09:20 | 10,7 | colorless, clear | 0,80 | 7,82 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088143 | Tank vehicle KWW 41, clutch pipe delivery | 29.02.2024 | - | - | - | - | - | - | sampling not possible: tank vehicle in repair shop | | | | | |
| 240088150 | Tank vehicle KWW 42, clutch pipe delivery | 28.02.2024 | 08:50 | 11,4 | colorless, clear | 0,81 | 8,02 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088202 | Tank vehicle KWW 43, clutch pipe delivery | 28.02.2024 | 08:45 | 10,9 | colorless, clear | 0,69 | 7,82 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088205 | Tank vehicle KWW 44, clutch pipe delivery | 28.02.2024 | 09:30 | 10,3 | colorless, clear | 0,82 | 7,78 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088207 | Tank vehicle KWW 45, clutch pipe delivery | 28.02.2024 | 09:45 | 11,0 | colorless, clear | 0,80 | 7,70 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088209 | Tank vehicle KWW 46, clutch pipe delivery | 28.02.2024 | 09:05 | 9,9 | colorless, clear | 0,78 | 7,76 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |



To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BVD-4500790807
report 6782611 (February 2024)**

| Sample ID | Sample designation | Sampling day | Sampling time | Water temperature °C | Description | Free chlorine mg/l | pH-value | Turbidity NTU | DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100 | DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100 | Escherichia coli KBE/100 ml Limit Value 0 | Coliforms KBE/100 ml Limit Value 0 | Pseudomonas aeruginosa KBE/100 ml Limit Value 0 | Enterococci KBE/100 ml Limit Value 0 |
|-----------|---|--------------|---------------|----------------------|------------------|--------------------|----------|---------------|--|--|---|------------------------------------|---|--------------------------------------|
| 240088212 | Tank vehicle KWW 47, clutch pipe delivery | 29.02.2024 | - | - | - | - | - | - | sampling not possible: tank vehicle in repair shop | | | | | |
| 240088214 | Tank vehicle KWW 48, clutch pipe delivery | 28.02.2024 | 09:35 | 10,3 | colorless, clear | 0,84 | 7,55 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088215 | Tank vehicle KWW 49, clutch pipe delivery | 28.02.2024 | 09:10 | 10,4 | colorless, clear | 0,75 | 7,78 | 0,8 | 0 | 0 | 0 | 0 | 0 | 0 |
| 240088217 | Tank vehicle KWW 50, clutch pipe delivery | 28.02.2024 | 09:55 | 10,2 | colorless, clear | 0,76 | 7,83 | 0,7 | 0 | 0 | 0 | 0 | 0 | 0 |

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Taususstein, March 11th, 2024

The laboratory sites of the SGS group Germany according to the abbreviations mentioned above including the corresponding accreditation process numbers are listed at <http://www.institut-fresenius.de/filestore/89/laborstandortkuerzlistgs.pdf>.

*** End of test report ***

This document is issued by the Company subject to its General Conditions of Service (www.sgs.de). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein. This document is an original. If the document is submitted digitally, it is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its client and this document does not exonerate parties to a transaction from exercising all their rights and under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.