

To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

Report on the samples being taken by our field service - Your Order No.: BVD-4500790807
report 6875336 (April 2024)

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	Turbidity NTU	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
240318791	Drinking water Delivery Tap 1	30.04.2024	09:55	13,9	colorless, clear	0,91	7,68	0,4	0	0	0	0	0	0
240318792	Drinking water Delivery Tap 2	30.04.2024	-	-	-	-	-	-	sampling not possible: delivery tap is dismantled					
240318794	Drinking water Delivery Tap 3	30.04.2024	10:05	14,0	colorless, clear	0,97	7,65	0,4	0	0	0	0	0	0
240318795	Drinking water Delivery Tap 4	30.04.2024	10:30	13,7	colorless, clear	1,08	7,67	0,5	0	0	0	0	0	0
240318796	Tank vehicle KWW 36, clutch pipe delivery	30.04.2024	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
240318798	Tank vehicle KWW 38, clutch pipe delivery	30.04.2024	09:00	17,1	colorless, clear	0,77	7,80	0,4	0	0	0	0	0	0
240318799	Tank vehicle KWW 39, clutch pipe delivery	30.04.2024	09:30	16,6	colorless, clear	0,75	7,94	0,4	0	0	0	0	0	0
240318800	Tank vehicle KWW 41, clutch pipe delivery	30.04.2024	08:25	15,1	colorless, clear	0,88	7,66	<0,1	0	0	0	0	0	0
240318852	Tank vehicle KWW 42, clutch pipe delivery	30.04.2024	08:45	16,0	colorless, clear	0,75	7,75	0,1	0	0	0	0	0	0
240318853	Tank vehicle KWW 43, clutch pipe delivery	30.04.2024	08:20	14,2	colorless, clear	0,74	7,69	0,4	0	0	0	0	0	0
240318854	Tank vehicle KWW 44, clutch pipe delivery	30.04.2024	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					
240318855	Tank vehicle KWW 45, clutch pipe delivery	30.04.2024	08:35	17,7	colorless, clear	0,70	7,95	0,4	0	2	0	0	0	0
240318856	Tank vehicle KWW 46, clutch pipe delivery	30.04.2024	-	-	-	-	-	-	sampling not possible: tank vehicle in repair shop					



To: Fraport AG, Flughafen Frankfurt Bodenverkehrsdienste

**Report on the samples being taken by our field service - Your Order No.: BYD-4500790807
report 6875336 (April 2024)**

Sample ID	Sample designation	Sampling day	Sampling time	Water temperature °C	Description	Free chlorine mg/l	pH-value	Turbidity NTU	DEV agar after 44 ± 4 h at 20 ± 2°C KBE/ml Limit Value 100	DEV agar after 44 ± 4 h at 36 ± 1°C KBE/ml Limit Value 100	Escherichia coli KBE/100 ml Limit Value 0	Coliforms KBE/100 ml Limit Value 0	Pseudomonas aeruginosa KBE/100 ml Limit Value 0	Enterococci KBE/100 ml Limit Value 0
240318859	Tank vehicle KWW 47, clutch pipe delivery	30.04.2024	08:50	17,3	colorless, clear	0,77	7,84	0,4	0	0	0	0	0	0
240318860	Tank vehicle KWW 48, clutch pipe delivery	30.04.2024	09:20	15,7	colorless, clear	0,87	7,88	0,4	0	0	0	0	0	0
240318861	Tank vehicle KWW 49, clutch pipe delivery	30.04.2024	09:05	17,5	colorless, clear	0,79	7,81	0,3	0	0	0	0	0	0
240318862	Tank vehicle KWW 50, clutch pipe delivery	30.04.2024	09:10	16,3	colorless, clear	0,86	7,82	0,4	0	0	0	0	0	0

Assessment:

The microbiological quality of all tested samples is unobjectionable according to German drinking water regulations as far as examined.

SGS INSTITUT FRESENIUS GmbH

Tausenstein, May 13th, 2024

The laboratory sites of the SGS group Germany according to the abbreviations mentioned above including the corresponding accreditation process numbers are listed at <http://www.institut-fresenius.de/filestore/89/labstandortkuerzlistsgs.pdf>.

*** End of test report ***

This document is issued by the Company subject to its General Conditions of Service (www.sgs-group.de/agb). Attention is drawn to the limitations of liability, indemnification and jurisdictional issues established therein. This document is an original. If the document is submitted digitally, it is to be treated as an original within the meaning of UCP 600. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of client's instructions, if any. The Company's sole responsibility is to its client and this document does not exonerate parties to a transaction from exercising all their rights and under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.